

FIG. 1





FIG. 2



SCANNING EXPOSURE DIRECTION



09064648-092801

FIG. 3




FIG. 4





FIG. 5A



WHEN EVALUATION VALUE IS IN STATIC EXPOSURE AREA,
FORCIBLY CORRECT IT TO SCANNING EXPOSURE AREA

FIG. 5B




FIG. 6




FIG. 7




FIG. 8A




FIG. 8B






FIG. 9



09964648-09201

FIG. 10



0964643-09301
108260-04949650

FIG. 11

URL

TROUBLE DB INPUT SCREEN

DATE OF OCCURRENCE ~ 1404

MODEL ~ 1401

CASE NAME ~ 1403

DEVICE ~ 1402

EMERGENCY LEVEL ~ 1405


SYMPTOM ~ 1406

REMEDY ~ 1407

PROGRESS ~ 1408

1410 1411 1412

[LINK TO RESULT LIST DATABASE](#) [SOFTWARE LIBRARY](#) [OPERATION GUIDE](#)

FIG. 12

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

0954648-092201

FIG. 13

